



# Devon Diesel Society

## Owners and Operators of heritage locomotives Class 04 D2246, Class 37 D6737 and Class 50 D402

### Working Party Report – Mar 16

The 5 working parties of March directed their efforts solely on D6737 with various tasks undertaken.

Work concentrated around the area of the main and auxiliary generators following an inspection of the commutator and brush gear. These were found to be particularly dirty and the decision taken to remove the brush gear and



clean all areas. Firstly, the auxiliary generator brush gear was removed and then the following weekend the main, these were then transferred off site for overhaul by a local company's apprentices. The generators together with

the area within the engine room around them was hoovered, cleaned down and repainted.

No 2 end nose had the lighting module refitted following painting and the former route indicator boxes were stripped of their old wiring and prepared for the fitting of new. Lastly some DSD pipework was refitted to the nose following cleaning and painting.

